


CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

7N23-28-2

Document Number

City of _____

County of MONO, CaliforniaBrief Legal Description NE. CORNER SECTION 28, T. 7 N., R. 23 E., M.D.B. & M.**CORNER TYPE**

Government Corner ☒ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey 11-3-05

COORDINATES (Optional)

N. 108766.15
 E. 100279.77 ASSUMED
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial ☒

Corner - Left as found Found and tagged Established Reestablished ☒ Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SET 2 1/4" "CADT" BRASS CAP IN A 1 1/4" O.D. X 30" GALVANIZED PIPE,
WITH CONCRETE, UP 0.5', STAMPED AS SHOWN ON REVERSE. BUILT
SMALL ROCK MOUND AROUND PIPE AND SET METAL WITNESS POST
AND PADDLE 3.0' WESTERLY.


A description of the physical condition of the monument as found and as set or reset: ORIGINAL MONUMENT
AS SHOWN ON CORNER RECORD FILED OCT. 10, 1986 WAS
DESTROYED DURING FLOOD OF 1999, ALONG WITH ALL BEARING TREES.
RESET BASED ON PREVIOUS TIES FROM NEARBY CONTROL POINTS.
SEE RECORD OF SURVEY MAP

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on NOVEMBER 3, 2005.

Signed Karla A. Riesen P.L.S. or R.G.E. Number 7285
 For the State of California
 Department of Transportation

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received Dec 27, 2005 and examined
 and filed Jan 20, 2006

Signed John S. Parrish P.L.S. or R.G.E. Number 5050Title Monro County Surveyor

County Surveyor's Comment _____

